



APPROVED SERVICE HARDWARE			
		MUELLER	FORD
	2" PVC	H-13420	S70
SADDLE	UP TO 8"	SEE NOTE	FC 101
BALL CORPORATION		B-25008	FB1000G
YOKE		H-5020	Y 502
ANGLE BALL VALVE		B-24273	BA94-323WG
CHECK VALVE		H-14247-A	HHS91-323
CONNECTORS	COPPER	STYLE 110	GRIP JOINT
EXPANSION CONNECTION			EC 23

NOTE:
 ROMAC 101N SHALL REPLACE MUELLER FOR PIPE
 DIAMETER UP TO 8"

SMITH BLAIR 317, FORD FC 202 OR ROMAC 202N SHALL
 REPLACE MUELLER FOR PIPE DIA. 12" AND UP